

To

The Principal,  
P.M. Shri Govt Girls  
Sr. Sec. School  
Beri-3080, Jhajjar.

Memo No.

5287

Dated:

29/04/2024

**Subject:** विद्यालय की Building Safety NOC बारे।

**Reference:** Your letter no. 2024/84 dated 26.04.2024.

In respect of above subject, it is submitted that this office has already issued structure safety certificate addressed to the District Education Officer vide this office memo no. 11929 dated 20.07.2023 (copy attached). Hence there is no question arise to issue NOC again.

In the context of school Name, this office received a letter from District Education Officer, G-1-23/069-70 dated 23.06.2023 in which your school name was mentioned as GGSSS Beri (copy attached). Now, as it has renamed to P.M. Shri Govt. Girls Sr. Sec. School Beri, so the NOC issued earlier must be considered on current name of your school.

This is for your information and necessary action.

DA/As above

Executive Engineer,  
Provincial Division, PWD B&R Br.,  
Jhajjar.

Endst No.

Dated:

Copy forwarded to the District Education Officer, Jhajjar for information and necessary action.

DA/As above

Executive Engineer,  
Provincial Division, PWD B&R Br.,  
Jhajjar.

Principal

P.M. Shri G.G.S.S.S.  
BERI-3080 (Jhajjar)

# HARYANA PWD (B&R) DEPARTMENT

JHAJJAR,

Stadium Chowk, Near Shriram Park,

Tel. No. 01251-252085

Email ID: pwd-eeepd-jhajjar@hry.nic.in



To

The District Education Officer,  
Jhajjar.

Memo No. 11929

Dated: 20/07/2023

Subject: राजकीय PM SHRI वरिष्ठ माध्यमिक विद्यालयों को केन्द्रीय माध्यमिक शिक्षा बोर्ड (CBSE) से सम्बन्धता हेतु certificate on structure safety certificate प्राप्त करने बारे ।

Reference: Your memo no. G-I-23/1069-70 dated 23.06.2023.

On the subject noted above, the Sub Divisional Engineer, Provincial Sub Division No-2, PWD B&R Br., Beri has reported that he has inspected the Building of G.S.S.S. Beri alongwith concerned J.E and the teaching staff of this School on dated 05.07.2023. The class rooms, offices, labs were inspected visually. Main office of School and old class rooms, labs have no cracks on walls, windows are in good condition. R.C.C. slabs ceiling have smooth surface. Bottom plaster of first floor veranda above main office is cracked and steel of the beam is exposed from bottom at two/three locations.

The bottom plaster of slab of main staff room indicated as room no. 13 has damaged and steel is exposed. The level of school building is down as compared to adjoining road level. Photographs of the same are attached herewith.

This is submitted for information and necessary action.

DA/Photographs

Executive Engineer,  
Provincial Division, PWD B&R Br.,  
Jhajjar

Endst No. 11930

Dated: 20/07/2023

Copy of above is forwarded to the Sub Divisional Engineer, Provincial Sub Division No-2, PWD B&R Br., Beri w.r.t. his memo no. 515 dated 07.07.2023 for information.

DA/Nil

Executive Engineer,  
Provincial Division, PWD B&R Br.,  
Jhajjar

1074 (S23)

WP

Principal

P.M. Shri G.G.S.S.S.  
BERI-3080 (Jhajjar)